

Re-worked UltraLinks


How to identify a re-worked device

All recalled UltraLink devices from the affected batches, which have been re-worked in our factory, have been Dot-matrix marked with a letter 'A'.

The re-work marking is located on the side of the guard which surrounds the spring-loaded button. This 'A' marking enables users and PPE Inspectors to identify that a device that falls within the recalled batch range, has undergone rework, and has been deemed suitable for return to service.



Batches Subject to Recall:



LK100A1.2



LK101A1.2

Affected batches:

LK100A1.2:

From 170431 to 177209, inclusive

LK101A1.2:

From 170433 to 176974, inclusive

PLEASE NOTE!

Any devices bearing serial numbers that fall within the range of affected (recalled) devices, but **DO NOT** bear the official re-work marking, must be **removed from service IMMEDIATELY**

These devices must be registered for recall, using the button below:



Units that are marked with batch numbers outside of the above batch number ranges, are not subject to recall.

Please contact us if you require further information.